Piper PA-28R-201

Airworthiness Directives Compliance Report

Date: 6/24/2026	Tail #: N289ND	
Airframe: Piper PA-28R-201	S/N: 28-44039	Hours: ACTT: 8286.8 | Hobbs: 1573.1 | Tach: 8286.8
Engine: Lycoming IO-360-C1C6	S/N: L-157450-51E	Hours:
Propeller: McCauley B2D34C Series	S/N:	Hours:

Airframe: Piper PA-28R-201

AD# Eff Date Subject Category		Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
62-19-03 06/28/62 Airframe	Propeller Attachment Bolts	6-24-2026	Not Applicable by S/N			ALBERTO HERRERA IA 3698853
64-06-06 04/06/64 Airframe	Control Wheel Assembly	6-24-2026	Not Applicable by S/N	Yes		ALBERTO HERRERA IA 3698853
67-20-04 03/27/67 Airframe	Main Landing Gear Link	6-24-2026	Not Applicable. Not Installed			ALBERTO HERRERA IA 3698853
67-25-02 05/22/68 Airframe	Fuel Selector Valve	6-24-2026	Not Applicable by model			ALBERTO HERRERA IA 3698853
72-04-03 Airframe	Superseded By 76-25-06	6-24-2026	Superseded By 76-25-06			ALBERTO HERRERA IA 3698853
76-25-06 Airframe	Superseded By 95-26-13	6-24-2026	Superseded By 95-26-13			ALBERTO HERRERA IA 3698853
77-23-03 11/14/77 Airframe	Engine Control Rod End Bearings	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
78-02-05 01/29/79 Airframe	Fuel Flow	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
79-13-03 06/08/79 Airframe	Fire Hazard Prevention	6-24-2026	Not applicable by S/N	Yes* (Terminating Action)		ALBERTO HERRERA IA 3698853
79-22-02 10/26/79 Airframe	Fuel Leakage	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
80-14-03 07/01/80 Airframe	Radio Muting Relay Plug	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
80-19-01 08/12/80 Airframe	Carbon Monoxide in Cabin	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
80-24-03 Airframe	Superseded By 86-17-01	6-24-2026	Superseded By 86-17-01			ALBERTO HERRERA IA 3698853
81-11-02 R1 10/02/81 Airframe	Oil Drain Valves	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
82-06-11 R1 06/16/82 Airframe	Nose Landing Gear	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
86-17-01 08/21/86 Airframe	Ammeter Replacement	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
87-08-08 R3 05/22/89 Airframe	Rescission of 87-08-08 and Subsequent Revisions	6-24-2026	Rescission of 87-08-08 and Subsequent Revisions			ALBERTO HERRERA IA 3698853
94-14-14 06/13/94 Airframe	Nose Landing Gear Modification	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
95-20-07 Airframe	Superseded By 97-01-01	6-24-2026	Superseded By 97-01-01			ALBERTO HERRERA IA 3698853
95-26-13 Airframe	Superseded By 17-14-04	6-24-2026	Superseded By 17-14-04			ALBERTO HERRERA IA 3698853
96-10-03 06/14/96 Airframe	Flap Handle Bolt	6-24-2026	Not applicable by S/N			ALBERTO HERRERA IA 3698853
97-01-01 R1 12/08/98 Airframe	Main Gear Sidebrace Stud	6-24-2026	Not applicable by S/N	Yes* (Terminating Action)		ALBERTO HERRERA IA 3698853
2004-14-12 08/10/04 Airframe	Control Wheel Attaching Hardware	7/13/04 @ 2938.7 ACT	PCW- See aircraft logs			ALBERTO HERRERA IA 3698853
2010-15-10 08/31/10 Airframe	Control Wheel Shafts	12/23/10 @ 7132.4 ACTT	PCW- See aircraft logs			ALBERTO HERRERA IA 3698853

2013-02-13 03/11/13 Airframe	Stabilator Control System	7/12/13@7118.6 ACTT	PCW- See aircraft logs	Yes		ALBERTO HERRERA IA 3698853
2019-20-13 Airframe	Superseded By 18-07-21	6-24-2026	Superseded By 18-07-21			ALBERTO HERRERA IA 3698853
2018-07-21 04/26/18 Airframe	Wing Rib Cracks	5/25/16 @ 7215.0	PCW- See aircraft logs			ALBERTO HERRERA IA 3698853
2017-14-04 08/15/17 Airframe	Oil Cooler Hose Assemblies	12/1/17 @ACTT 7744.4	Complied with by replacement of oil cooler hoses with type D hoses	Yes* (Terminating Action)		ALBERTO HERRERA IA 3698853
2018-02-05 Airframe	Superseded By 18-07-03	6-24-2026	Superseded By 18-07-03			ALBERTO HERRERA IA 3698853
2018-07-03 04/20/18 Airframe	Fuel Tank Selector Cover Placards	6/24/2026 ACTT 8288.8	C/W by Inspection of Placard - No Defects Noted			ALBERTO HERRERA IA 3698853
2020-26-16 02/16/21 Airframe	Wing Separation by Main Spar Cap Fatigue Cracking	6-24-2026@8286.8	Complied with Inspection, no defect noted	Yes	6-31-2027@8396.8	ALBERTO HERRERA IA 3698853
2024-10-04 06/06/24 Airframe	Rear Wing Spar Attachment Fitting	6-24-2026@8286.8	Complied with Inspection, no defect noted		8-31-2027@8396.8	ALBERTO HERRERA IA 3698853

Engine: Lycoming IO-360-C1C6

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
66-20-04 08/27/66 Engine	Oil Filter Adapter Gasket		N/A			ALBERTO HERRERA IA 3698853
71-05-02 02/13/73 Engine	Crankcase Main Bearings		N/A	Yes* (Terminating Action)		ALBERTO HERRERA IA 3698853
71-11-02 03/14/72 Engine	Intake and Exhaust Hydraulic Tappet Plunger Assembly		N/A			ALBERTO HERRERA IA 3698853
73-23-01 01/13/77 Engine	Piston Pin Cracks From Grinding		N/A			ALBERTO HERRERA IA 3698853
75-06-09 05/13/77 Engine	Oil Pump Drive Shaft and Impeller		N/A			ALBERTO HERRERA IA 3698853
75-09-15 04/30/75 Engine	Bendix Fuel Injector Flow Divider Cover Gasket		N/A			ALBERTO HERRERA IA 3698853
78-23-10 11/07/78 Engine	Bendix RSA Series Fuel Injector Bellows Seal		N/A			ALBERTO HERRERA IA 3698853
79-04-05 09/26/79 Engine	Bendix RSA Series Fuel Injectors Diaphragm		N/A			ALBERTO HERRERA IA 3698853
81-18-04 R2 Engine	Superseded By 96-09-10	6-24-2026	Superseded By 96-09-10			ALBERTO HERRERA IA 3698853
90-04-06 R1 05/28/91 Engine	Propeller Governor External Oil Leak		N/A			ALBERTO HERRERA IA 3698853
91-14-22 Engine	Superseded By 04-10-14		Superseded By 04-10-14			ALBERTO HERRERA IA 3698853
92-12-05 07/10/92 Engine	Piston Pin Failure		N/A			ALBERTO HERRERA IA 3698853
92-20-07 Engine	Superseded By 93-05-21	6-24-2026	Superseded By 93-05-21			ALBERTO HERRERA IA 3698853
93-02-05 Engine	Superseded By 02-26-01	6-24-2026	Superseded By 02-26-01			ALBERTO HERRERA IA 3698853
93-05-21 Engine	Superseded By 93-11-11	6-24-2026	Superseded By 93-11-11			ALBERTO HERRERA IA 3698853
93-05-22 Engine	Superseded By 02-26-01	6-24-2026	Superseded By 02-26-01			ALBERTO HERRERA IA 3698853
93-11-11 06/21/50 Engine	Delphi/Slick Fuel Pumps Overhauled (by AA!) - Remove Affected Pump and Replace		N/A			ALBERTO HERRERA IA 3698853
94-14-13 Engine	Superseded By 95-26-02	6-24-2026	Superseded By 95-26-02			ALBERTO HERRERA IA 3698853
95-07-01 04/12/95 Engine	Superior Air Parts Connecting Rod Bolts		N/A			ALBERTO HERRERA IA 3698853
95-26-02 01/24/96 Engine	Detonation Due To Low Octane		N/A			ALBERTO HERRERA IA 3698853
96-09-10 07/15/96 Engine	Oil Pump Impeller Failure		N/A			ALBERTO HERRERA IA 3698853

06-23-03 12/17/96 Engine	High Pressure Fuel Pumps		N/A			ALBERTO HERRERA IA 3698853
97-01-03 Engine	Superseded By 97-15-11	6-24-2026	Superseded By 97-15-11			ALBERTO HERRERA IA 3698853
97-15-11 08/12/97 Engine	Piston Pin Failure		N/A			ALBERTO HERRERA IA 3698853
98-02-08 03/30/98 Engine	Crankshaft Corrosion Pits		N/A	Yes		ALBERTO HERRERA IA 3698853
98-17-11 10/19/98 Engine	Crankshafts Installed by Nelson Balancing Service		N/A			ALBERTO HERRERA IA 3698853
08-18-12 Engine	Superseded By 03-14-03	6-24-2026	Superseded By 03-14-03			ALBERTO HERRERA IA 3698853
2002-26-01 Engine	Superseded By 08-14-07	6-24-2026	Superseded By 08-14-07			ALBERTO HERRERA IA 3698853
2003-14-03 08/14/03 Engine	Rotary Fuel Pump Leaks		N/A	Yes* (Terminating Action)		ALBERTO HERRERA IA 3698853
2004-10-14 08/25/04 Engine	Crankshaft Gear Retaining Bolt	6-24-2026	Due at Prop Strike	Yes		ALBERTO HERRERA IA 3698853
2005-19-11 10/21/05 Engine	Crankshaft Failures	6-24-2026	Not Applicable - Not Installed			ALBERTO HERRERA IA 3698853
2006-05-16 04/27/06 Engine	Crankshaft Failure	6-24-2026	Not Applicable - Not Installed			ALBERTO HERRERA IA 3698853
2006-20-09 Engine	Superseded By 12-19-01	6-24-2026	Superseded By 12-19-01			ALBERTO HERRERA IA 3698853
2008-08-14 Engine	Superseded By 09-02-03	6-24-2026	Superseded By 09-02-03			ALBERTO HERRERA IA 3698853
2008-14-07 Engine	Superseded By 11-26-04	6-24-2026	Superseded By 11-26-04			ALBERTO HERRERA IA 3698853
2009-02-03 02/09/09 Engine	RSA-5 or RSA-10 Series - Fuel Injection Servo Plug Gasket		N/A	Yes* (Terminating Action)		ALBERTO HERRERA IA 3698853
2011-15-10 Engine	Superseded By 12-03-06	6-24-2026	N/A			ALBERTO HERRERA IA 3698853
2011-26-04 Engine	Superseded By 15-19-07	6-24-2026	Superseded By 15-19-07			ALBERTO HERRERA IA 3698853
2012-03-06 02/24/12 Engine	AVStar Fuel Servo Diaphragm		N/A			ALBERTO HERRERA IA 3698853
2012-19-01 10/24/12 Engine	Crankshaft Replacement		N/A			ALBERTO HERRERA IA 3698853
2015-19-07 11/03/15 Engine	Fuel Injector Fuel Lines and Clamps	6-24-2026@8286.8	C/W by Inspection - no defects noted	Yes	6-31-2027@8386.8	ALBERTO HERRERA IA 3698853
2017-16-11 08/15/17 Engine	Connecting Rod Failure		N/A			ALBERTO HERRERA IA 3698853
2022-16-03 08/15/22 Engine	S-1200 Series Magneto Roller Bearings		N/A			ALBERTO HERRERA IA 3698853
2024-21-02 Engine	Superseded By 2026-04-11	6-24-2026	Superseded By 2026-04-11			ALBERTO HERRERA IA 3698853
2026-04-11 04/08/26 Engine	Connecting Rod Failure		N/A	Yes* (Terminating Action)		ALBERTO HERRERA IA 3698853

Propeller: McCauley B2D34C Series

AD# Eff Date Subject Category		Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
68-06-04 Propeller	Superseded By 77-20-03	6-24-2026	Superseded By 77-20-03			ALBERTO HERRERA IA 3698853
70-04-01 02/20/70 Propeller	Blade Damage	6-24-2026	N/A			ALBERTO HERRERA IA 3698853
70-04-02 Propeller	Superseded By 77-17-09	6-24-2026	Superseded By 77-17-09			ALBERTO HERRERA IA 3698853
75-24-12 Propeller	Superseded By 77-17-09	6-24-2026	Superseded By 77-17-09			ALBERTO HERRERA IA 3698853
77-17-09 Propeller	Superseded By 91-15-04	6-24-2026	Superseded By 91-15-04			ALBERTO HERRERA IA 3698853
77-19-01 Propeller	Superseded By 78-20-01	6-24-2026	Superseded By 78-20-01			ALBERTO HERRERA IA 3698853

77-20-03 Propeller	Superseded By 91-15-04	6-24-2026	Superseded By 91-15-04			ALBERTO HERRERA IA 3698853
77-23-01 Propeller	Superseded By 91-15-04	6-24-2026	Superseded By 91-15-04			ALBERTO HERRERA IA 3698853
77-24-04 Propeller	Superseded By 91-15-04	6-24-2026	Superseded By 91-15-04			ALBERTO HERRERA IA 3698853
78-20-01 Propeller	Superseded By 91-15-04	6-24-2026	Superseded By 91-15-04			ALBERTO HERRERA IA 3698853
82-27-02 R1 02/22/83 Propeller	Dye Penetrant Inspection For Blade Shank Area Cracks	6-24-2026	N/A			ALBERTO HERRERA IA 3698853
91-15-04 08/07/91 Propeller	Blade Threaded Retention Area	6-24-2026	N/A			ALBERTO HERRERA IA 3698853
2003-13-17 07/18/03 Propeller	T and W Serviced Propellers	6-24-2026	Not Applicable - Not worked by T&W			ALBERTO HERRERA IA 3698853
2005-14-11 08/17/05 Propeller	Southern California Propeller Serviced Propellers	6-24-2026	Not Applicable - Not worked by SCPS			ALBERTO HERRERA IA 3698853
2006-24-07 01/03/07 Propeller	Oxford Aviation/CSE Aviation Serviced Propellers	6-24-2026	Not Applicable - Not worked by CSE			ALBERTO HERRERA IA 3698853