Piper PA-32-260

Airworthiness Directives Compliance Report

Date: 4/24/2026	**Tail #:** N130GH	
Airframe: Piper PA-32-260	**S/N:** 32-124	**Hours:** TT: 4959.33 Tach: 4959.33 TSMOH: 1728.61
Engine: Lycoming O-540-E4B5	**S/N:**	**Hours:**
Propeller: Hartzell HC-C2Y Series	**S/N:**	**Hours:**

Airframe: Piper PA-32-260

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
67-26-03 04/12/68 Airframe	Fuel System Screens and Filters	4/28/26 4959.33	PCW		Yes	PCW	Jeff Bowers 3051002
69-22-02 07/30/79 Airframe	Failure of Control Wheel		PCW	Ramhorns	Yes* (Terminating Action)	N/A	Jeff Bowers 3051002
70-26-04 06/24/71 Airframe	Stabilizer Balance Weight Tube		PCW	Upbotal tube	Yes	PCW	Jeff Bowers 3051002
72-08-06 04/14/72 Airframe	Landing Gear Torque Links		N/A by PN		Yes	N/A	Jeff Bowers 3051002
75-10-03 05/12/75 Airframe	Forward Baggage Door Delamination		PCW		Yes* (Terminating Action)	N/A PCW	Jeff Bowers 3051002
75-24-02 11/21/75 Airframe	Quick-Disconnect Seats Rear Legs Inspection		C/W by inspection	Installed Placard	Yes	4/28/27 100 hrs	Jeff Bowers 3051002
77-12-01 06/10/77 Airframe	Fuel System Malfunction		PCW	Parts A+E	Yes	5059.33	Jeff Bowers 3051002
78-23-01 11/03/78 Airframe	Fuel Drain Lever Cover Door		PCW Part B		Yes	5059.33	Jeff Bowers 3051002
2013-02-13 03/11/13 Airframe	Stabilator Control System		PCW	SB1245A	Yes	6959.33 2033	Jeff Bowers 3051002
2017-14-04 08/15/17 Airframe	Oil Cooler Hose Assemblies		C/W by inspection		Yes* (Terminating Action)	4/28/27 100 hrs	Jeff Bowers 3051002
2020-24-05 12/28/20 Airframe	Main Wing Spar Corrosion		PCW		Yes	2031	Jeff Bowers 3051002
2020-26-16 02/16/21 Airframe	Wing Separation by Main Spar Cap Fatigue Cracking		N/A By TT		Yes	N/A	Jeff Bowers 3051002
2023-09-09 07/17/23 Airframe	Exhaust Tailpipe V-Band Coupling		N/A Non turbo		Yes	N/A	Jeff Bowers 3051002

Engine: Lycoming O-540-E4B5

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
63-14-03 07/06/63 Engine	Oil Pump Drive Shaft		N/A by O'haul date		Yes* (Terminating Action)	N/A	Jeff Bowers 3051002
99-04-04 02/25/99 Engine	Magneto magneto Model numbers 6251, 6252, 6255, 6351 and 6355 - Magneto Impulse Coupling		C/W by insp		Yes	Replace 5005.42	Jeff Bowers 3051002
2004-10-14 06/25/04 Engine	Crankshaft Gear Retaining Bolt		N/A By MM		Yes	N/A	Jeff Bowers 3051002
2009-26-12 02/04/10 Engine	ECi Cracked Cylinder Assemblies		Not ECI cylinders		Yes	N/A	Jeff Bowers 3051002
2026-04-11 04/08/26 Engine	Connecting Rod Failure		Screen Visual insp		Yes* (Terminating Action)	@ oil Change	Jeff Bowers 3051002

Propeller: Hartzell HC-C2Y Series							
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
64-20-01 08/28/64 Propeller	Pitch Change Blocks	4/28/26 4959.33	N/A By SN.		Yes* (Terminating Action)	N/A	Jeff Bowers 3051002
2001-23-08 12/24/01 Propeller	Hub Fillet Radius Crack Inspection		N/A By SN.		Yes* (Terminating Action)	N/A	Jeff Bowers 3051002
2008-13-28 07/17/08 Propeller	Hub Blade Socket Lubrication Hole Cracks		N/A By not L turnoy		Yes* (Terminating Action)	N/A 1time	Jeff Bowers 3051002
2009-22-03 11/12/09 Propeller	Propeller Hub Crack Inspection		N/A		Yes* (Terminating Action)	N/A 1time	Jeff Bowers 3051002